



2106 Gordon Street,
Guelph, ON
N1L 1G6
Phone: 1-800-424-2856 or 519-824-5600
Fax: 1-888-662-9479 or 519-824-6497
Website: www.cvo.org
Accreditation Contact: Louise Hamilton
ext. 2230 lhamilto@cvo.org

RADIOLOGY REQUIREMENTS

If your facility contains a diagnostic x-ray machine, for each x-ray source in the facility, an application in accordance with section 6 or 7 of Ontario Regulation 861/90 made under the Occupational Health and Safety Act, has been reviewed and accepted by an inspector under the Act.

The CVO inspector will be requesting the registration number that is issued by the Ministry of Labour, following application being made as outlined above. This application should be made to:

Ministry of Labour
Radiation Protection Service
81A Resources Road
Weston, Ontario
M9P 3T1

Central Phone Number: (416) 235-5922

Fax: (416) 235-5926

There are 4 inspectors now and whoever answers the phone will direct your call to the appropriate person. The inspectors are not assigned to cover any particular geographical area. The applications are distributed among the inspectors as they are received.

The application can be sent via mail or fax.

Please note:

You must notify the Radiation Protection Service when:

- 1) you purchase a new x-ray machine; or
- 2) move the existing x-ray machine within the facility; or
- 3) the facility moves; or
- 4) if you purchase an additional x-ray machine e.g. dental, mobile; or
- 5) you give up possession of an x-ray source, or
- 6) the ownership of the facility changes.

The monitoring badges required under this section may be obtained through:

Health Canada, Radiation Protection Bureau
National Dosimetry Services
775 Brookfield Road
Ottawa, Ontario
K1A 1C1

Phone: (613) 954-6689
Fax: (613) 957-8698

Toll Free Phone: 1-800-261-6689
Toll free Fax: 1-800-252-6272